2019-09-27

Descri	

All vehicles equipped with On board diagnostics II (OBD II)

<u>INFORMATION</u>

BMW vehicles can incorporate numerous control modules, sensors and cameras that assist in various functions within the vehicle. During a collision, these systems can sustain damage in ways that are not visually evident. These components must be evaluated to ensure the vehicle is repaired in a manner that complies with BMW Repair Standards / Guidelines. A damaged component may have a direct effect on the vehicle operation.

Therefore, a preliminary complete vehicle diagnostic test must be performed before beginning repairs on a vehicle which was involved in a collision. A post-repair complete vehicle diagnostic test must also be carried out following repairs, to ensure complete and proper functionality.

BMW recommends that all repairs are performed by a trained technician.